




# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-05-24-3200- MPI-057
Rig Number:	HL99	Job No:	ATS-05-24-3200
Location:	Southern Rumila – RU-149	Page No:	01 of 02
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444

**PICTORIAL:**



**Item Description: MUD TANK**

SN	18058-1	18058-2	18058-3	18058-4
SN	18058-5	18058-6	18058-7	18058-8
SWL	50 KN			

**Unit Serial Number:**  
18058

**Details of inspection method(s):**  
Visible magnetic particle inspection

**Inspection Results:**  
MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

**Remarks: ACCEPTED**

Inspection Equipment Details			Personnel Details		Company Stamp
<b>Equipment</b>	Ac yoke		Inspector:	Aram Dlawar	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	05-01-2024		Date:	12-05-2024	
Calibration Due:	04-07-2024		Signature:		
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION				
Maker and Model	FLUXO	FLUXO	Supervisor:	Hasan Omran	
Type:	WCP-4	Black magnetic ink-3	Date:	13-05-2024	
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NET-F-001-1880E-3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)

Tel: +964 7833334444 +964 7822222633



# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-05-24-3200- MPI-057												
Rig Number:	HL99	Job No:	ATS-05-24-3200												
Location:	Southern Rumila – RU-149	Page No:	02 of 02												
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024												
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444												
<b>PICTORIAL:</b>					<b>Item Description: MUD TANK</b>										
					<table border="1"> <tr> <td>SN</td> <td>18058-1</td> <td>18058-2</td> <td>18058-3</td> <td>18058-4</td> </tr> <tr> <td>SN</td> <td>18058-5</td> <td>18058-6</td> <td>18058-7</td> <td>18058-8</td> </tr> <tr> <td>SWL</td> <td colspan="4">50 KN</td> </tr> </table>	SN	18058-1	18058-2	18058-3	18058-4	SN	18058-5	18058-6	18058-7	18058-8
SN	18058-1	18058-2	18058-3	18058-4											
SN	18058-5	18058-6	18058-7	18058-8											
SWL	50 KN														
<b>Unit Serial Number: 18058</b>															
<b>Details of inspection method(s):</b> Visible magnetic particle inspection															
<b>Inspection Results:</b> MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.															
<b>Remarks: ACCEPTED</b>															
<b>Inspection Equipment Details</b>			<b>Personnel Details</b>												
<b>Equipment</b>	Ac yoke		<b>Inspector:</b>	Aram Dlawar											
Serial Number	201504044		<b>Qualifications</b>	ASNT LEVEL II											
Calibration Date:	05-01-2024		<b>Date:</b>	12-05-2024											
Calibration Due:	04-07-2024		<b>Signature:</b>												
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION														
<b>Maker and Model</b>	FLUXO	FLUXO	<b>Supervisor:</b>	Hasan Omran											
Type:	WCP-4	Black magnetic ink-3	<b>Date:</b>	13-05-2024											
Batch Number	L230523/1	L230125/3													
Expiry Date:	23-05-2028	25-1-2025													

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)

Tel: +964 7833334444 +964 782222633