




Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-060
Rig Number:	HL99	Job No:	ATS-05-24-3200
Location:	Southern Rumila – RU-149	Page No:	01 of 02
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444

PICTORIAL:



Item Description: MUD TANK

SN	18062-1	18062-2	18062-3	18062-4
SN	18062-5	18062-6	18062-7	18062-8
SWL	50 KN			

Unit Serial Number:
18062

Details of inspection method(s):
Visible magnetic particle inspection

Inspection Results:
MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

Remarks: ACCEPTED

Inspection Equipment Details			Personnel Details		Company Stamp
Equipment	Ac yoke		Inspector:	Aram Dlawar	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	05-01-2024		Date:	12-05-2024	
Calibration Due:	04-07-2024		Signature:		
Consumables	MAGNETIC PARTICLES INSPECTION				
Maker and Model	FLUXO	FLUXO	Supervisor:	Hasan Omran	
Type:	WCP-4	Black magnetic ink-3	Date:	13-05-2024	
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 782222633



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-060												
Rig Number:	HL99	Job No:	ATS-05-24-3200												
Location:	Southern Rumila – RU-149	Page No:	02 of 02												
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024												
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444												
PICTORIAL:					Item Description: MUD TANK										
					<table border="1"> <tr> <td>SN</td> <td>18062-1</td> <td>18062-2</td> <td>18062-3</td> <td>18062-4</td> </tr> <tr> <td>SN</td> <td>18062-5</td> <td>18062-6</td> <td>18062-7</td> <td>18062-8</td> </tr> <tr> <td>SWL</td> <td colspan="4">50 KN</td> </tr> </table>	SN	18062-1	18062-2	18062-3	18062-4	SN	18062-5	18062-6	18062-7	18062-8
SN	18062-1	18062-2	18062-3	18062-4											
SN	18062-5	18062-6	18062-7	18062-8											
SWL	50 KN														
Unit Serial Number: 18062															
Details of inspection method(s): Visible magnetic particle inspection															
Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.															
Remarks: ACCEPTED															
Inspection Equipment Details			Personnel Details												
Equipment	Ac yoke		Inspector:	Aram Dlawar											
Serial Number	201504044		Qualifications	ASNT LEVEL II											
Calibration Date:	05-01-2024		Date:	12-05-2024											
Calibration Due:	04-07-2024		Signature:												
Consumables	MAGNETIC PARTICLES INSPECTION														
Maker and Model	FLUXO	FLUXO	Supervisor:	Hasan Omran											
Type:	WCP-4	Black magnetic ink-3	Date:	13-05-2024											
Batch Number	L230523/1	L230125/3													
Expiry Date:	23-05-2028	25-1-2025													

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 782222633