



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-063										
Rig Number:	HL99	Job No:	ATS-05-24-3200										
Location:	Southern Rumila – RU-149	Page No:	01 of 02										
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024										
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444										
PICTORIAL:		Item Description: CEMENT BLOCK											
		<table border="1"> <tr> <td>SN</td> <td>18071-1</td> <td>18071-2</td> <td>18071-3</td> <td>18071-4</td> </tr> <tr> <td>SWL</td> <td colspan="4">3 TONS</td> </tr> </table>		SN	18071-1	18071-2	18071-3	18071-4	SWL	3 TONS			
SN	18071-1	18071-2	18071-3	18071-4									
SWL	3 TONS												
		Unit Serial Number: CB-02											
		Details of inspection method(s): Visible magnetic particle inspection											
		Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.											
		Remarks: ACCEPTED											
Inspection Equipment Details			Personnel Details										
Equipment	Ac yoke		Inspector: Aram Dlawar										
Serial Number	201504044		Qualifications ASNT LEVEL II										
Calibration Date:	05-01-2024		Date: 12-05-2024										
Calibration Due:	04-07-2024		Signature:										
Consumables	MAGNETIC PARTICLES INSPECTION												
Maker and Model	FLUXO	FLUXO	Supervisor: Hasan Omran										
Type:	WCP-4	Black magnetic ink-3	Date: 13-05-2024										
Batch Number	L230523/1	L230125/3											
Expiry Date:	23-05-2028	25-1-2025											

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 782222633