



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-066										
Rig Number:	HL99	Job No:	ATS-05-24-3200										
Location:	Southern Rumila – RU-149	Page No:	01 of 02										
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024										
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444										
PICTORIAL:				Item Description: MUD TANK LADDER – Pad Eyes									
				<table border="1"> <tr> <td>SN:</td> <td>1</td> <td>2</td> <td>3</td> <td>4</td> </tr> <tr> <td>SWL:</td> <td colspan="4">3 TON</td> </tr> </table>		SN:	1	2	3	4	SWL:	3 TON	
SN:	1	2	3	4									
SWL:	3 TON												
				Unit Serial Number: LD-01									
				Details of inspection method(s): Visible magnetic particle inspection									
				Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.									
				Remarks: ACCEPTED									
Inspection Equipment Details			Personnel Details		Company Stamp 								
Equipment	Ac yoke		Inspector:	Aram Dlawar									
Serial Number	201504044		Qualifications	ASNT LEVEL II									
Calibration Date:	05-01-2024		Date:	12-05-2024									
Calibration Due:	04-07-2024		Signature:										
Consumables	MAGNETIC PARTICLES INSPECTION												
Maker and Model	FLUXO	FLUXO	Supervisor:	Hasan Omran									
Type:	WCP-4	Black magnetic ink-3	Date:	13-05-2024									
Batch Number	L230523/1	L230125/3											
Expiry Date:	23-05-2028	25-1-2025											

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 782222633