



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-067							
Rig Number:	HL99	Job No:	ATS-05-24-3200							
Location:	Southern Rumila – RU-149	Page No:	01 of 02							
Date of Inspection:	12-05-2024	Next Inspection Date:	11-11-2024							
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444							
PICTORIAL:			Item Description: TOOL BOX – Pad Eyes							
			<table border="1"> <tr> <td>SN:</td> <td>1</td> <td>2</td> <td>3</td> <td>4</td> </tr> <tr> <td>SWL:</td> <td colspan="4">1 T</td> </tr> </table>	SN:	1	2	3	4	SWL:	1 T
SN:	1	2	3	4						
SWL:	1 T									
			Unit Serial Number: TB-01							
			Details of inspection method(s): Visible magnetic particle inspection							
			Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.							
			Remarks: ACCEPTED							
Inspection Equipment Details		Personnel Details								
Equipment	Ac yoke	Inspector:	Aram Dlawar							
Serial Number	201504044	Qualifications	ASNT LEVEL II							
Calibration Date:	05-01-2024	Date:	12-05-2024							
Calibration Due:	04-07-2024	Signature:								
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:							
Maker and Model	FLUXO	FLUXO	Hasan Omran							
Type:	WCP-4	Black magnetic ink-3	Date:							
Batch Number	L230523/1	L230125/3	13-05-2024							
Expiry Date:	23-05-2028	25-1-2025								
			Company Stamp							

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 782222633