




# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>		Certificate Number:	ATS-05-24-3200- MPI-097	
Rig Number:	HL99		Job No:	ATS-05-24-3200	
Location:	Southern Rumila – RU-149		Page No:	01 of 01	
Date of Inspection:	16-05-2024		Next Inspection Date:	15-11-2024	
Type of Inspection	Visual inspection & MPI (Wet Visible Method)		Ref. Standards:	ASTM E709, ASTM E 1444	
<b>PICTORIAL:</b>			<b>Item Description:</b>		
			BIT BREAKER – Pad Eyes		
			<b>Unit Serial Number:</b>		
			2018HL0401		
	<b>Details of inspection method(s):</b>			Visible magnetic particle inspection	
<b>Inspection Results:</b>			MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.		
<b>Remarks:</b> ACCEPTED					
<b>Inspection Equipment Details</b>			<b>Personnel Details</b>		
<b>Equipment</b>	Ac yoke		Inspector:	Aram Dlawar	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	05-01-2024		Date:	16-05-2024	
Calibration Due:	04-07-2024		Signature:		
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION		Supervisor:	Hasan Omran	
Maker and Model	FLUXO	FLUXO	Date:	18-05-2024	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)  
 Tel: +964 7833334444 +964 782222633