



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of the Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with 4 columns: Client Name, Location of Examination, Certificate Number, Job Number, Date of Examination, Date of Certificate, Next Date of Examination, Last Date of Examination.

Table with 4 columns: Serial No. / Asset No., Description of The Equipment, Qty, SWL. Includes technical drawing of a Turnbuckle.

Reference Standard: BS EN 4429:1987

Table with 4 columns: Question, YES, NO, Was The Examination Carried Out? (6 Months, 12 Months, etc.)

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: None

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection: Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Table with 3 columns: Inspector Name, Qualifications & signature; Authenticated By; Stamp and Date.

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER".

ATS-LIF-F-002 ISSUE 3 - MAR 2021