




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU/149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-001	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
HL180102	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 2 1/2" GRADE: 6 Manufactured: J & L F.O.S: 6:1</p> 	1	55 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	Was The Examination Carried Out?			
	YES		NO	✓
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	✓	NO	In Accordance with an Examination Scheme? YES ✓ NO After the Occurrence of Exceptional Circumstances? YES NO ✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: **None**

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
 Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES ✓ NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-002	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
HL99 003 HL99 004 HL99 005 HL99 006	<p align="center">DEE SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 3/4”</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> 	4	25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	✓	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	✓	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	✓	NO		Within an Interval of 12 Months?	YES		NO	✓
					In Accordance with an Examination Scheme?	YES	✓	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	✓	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-003	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
09802	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 3/4”</p> <p>GRADE: 6</p> <p>Manufactured: BASH-P</p> <p>F.O.S: 6:1</p> 	1	25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-004	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
F3 F4 06	<p align="center">DEE SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/2”</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> 	3	17 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES			NO			Was The Examination Carried Out?			
							Within an Interval of 6 Months?	YES	✓	NO
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES			NO			Within an Interval of 12 Months?			
		✓					YES		NO	✓
	YES			NO			In Accordance with an Examination Scheme?			
							YES	✓	NO	
	YES			NO			After the Occurrence of Exceptional Circumstances?			
							YES		NO	✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally at The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-005	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
023	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/2” GRADE: 6 Manufactured: GT F.O.S: 6:1</p> 	1	17 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	Was The Examination Carried Out?			
	YES		NO	✓
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	✓	NO	In Accordance with an Examination Scheme? YES ✓ NO After the Occurrence of Exceptional Circumstances? YES NO ✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
 Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES ✓ NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-006	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
1701 1702	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/2” GRADE: 6 Manufactured: XW F.O.S: 6:1</p>	2	17 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date:
---	---	----------------------------



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024						
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024						
Certificate Number:	ATS-05-24-3200-007	Next Date of Examination:	10-Nov-2024						
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023						
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL						
H 11 H 12 015 S22	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4”</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p> 	4	12 Ton						
Reference Standards	BS EN 13889:2003 + A1:2008								
Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: NONE									
Is The Above a Defect Which is of Immediate Danger to Persons:						YES		NO	
Is The Above a Defect Which is not yet But Could Become a Danger to Persons:						YES by			
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:									
Particulars of any Tests Carried out as Part of the Examination: Visual Inspection: <i>Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:</i>									
Is this Equipment Fit for Purpose?						YES	√	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician			Authenticated By:  Majd Dayoub			Stamp and Date: 			

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-008	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
HL 38 HL 10	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4”</p> <p>GRADE: 6</p> <p>Manufactured: HK</p> <p>F.O.S: 6:1</p> 	2	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By:  Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-009	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
SP 10 SP 4	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p>	2	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-010	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
HL 12 HL A6	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4”</p> <p>GRADE: 6</p> <p>Manufactured: KEPRO</p> <p>F.O.S: 6:1</p>	2	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
--	---	--------------------------------



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024						
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024						
Certificate Number:	ATS-05-24-3200-011	Next Date of Examination:	10-Nov-2024						
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023						
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL						
05	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4”</p> <p>GRADE: 6</p> <p>Manufactured: ROBUR</p> <p>F.O.S: 6:1</p> 	1	12 Ton						
Reference Standards	BS EN 13889:2003 + A1:2008								
Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: NONE									
Is The Above a Defect Which is of Immediate Danger to Persons:						YES		NO	
Is The Above a Defect Which is not yet But Could Become a Danger to Persons:						YES by			
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:									
Particulars of any Tests Carried out as Part of the Examination: Visual Inspection: <i>Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:</i>									
Is this Equipment Fit for Purpose?						YES	√	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician			Authenticated By:  Majd Dayoub			Stamp and Date: 			

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-012	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
B3914 B3915 B3916 B3917 B3918 B3919 B3920 B3921 B3922 B3923 B3924 B3925	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8”</p> <p>GRADE: 6</p> <p>Manufactured: Toyolift</p> <p>F.O.S: 6:1</p>	12	9 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?				Was The Examination Carried Out?					
	YES		NO	√	Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
---	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-013	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
951 C 26 HL 95	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8”</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p>	3	9 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
--	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-014	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
S 301 S 230	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8” GRADE: 6 Manufactured: McKAT F.O.S: 6:1</p>	2	9 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES			NO			Was The Examination Carried Out?				
							Within an Interval of 6 Months?	YES	✓	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES			NO			Within an Interval of 12 Months?	YES		NO	✓
		✓					In Accordance with an Examination Scheme?	YES	✓	NO	
	YES			NO			After the Occurrence of Exceptional Circumstances?	YES		NO	✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
--	--	--------------------------------


THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-015	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
R 83	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8”</p> <p>GRADE: 6</p> <p>Manufactured: Crosby</p> <p>F.O.S: 6:1</p> 	1	9 1/2 Ton
Reference Standards	BS EN 13889:2003 + A1:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		√	Within an Interval of 6 Months?
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	√		In Accordance with an Examination Scheme?
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: NONE	YES	NO	After the Occurrence of Exceptional Circumstances?
	√		
Is The Above a Defect Which is of Immediate Danger to Persons:	YES	NO	
Is The Above a Defect Which is not yet But Could Become a Danger to Persons:	YES by		
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any Tests Carried out as Part of the Examination: Visual Inspection: Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:			
Is this Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
<p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	<p align="center">Majd Dayoub</p> 		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-016	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
B 5632 B 5633 B 5634 B 5635 B 2017 B 2018 B 2019 B 2021 B 2022 A 5286 A 4170	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1</p> 	11	8 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?				Was The Examination Carried Out?					
	YES		NO	√	Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?					Within an Interval of 12 Months?	YES		NO	√
	YES	√	NO		In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-017	Next Date of Examination:	10-Nov-2024
Job Number:	ATS--24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
113	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: SPY-A F.O.S: 6:1</p>	1	8 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES			NO			Was The Examination Carried Out?				
							Within an Interval of 6 Months?	YES	✓	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES			NO			Within an Interval of 12 Months?	YES		NO	✓
		✓					In Accordance with an Examination Scheme?	YES	✓	NO	
	YES			NO			After the Occurrence of Exceptional Circumstances?	YES		NO	✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-018	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
B 8333 D 3073 F 1056B	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: BASH-P F.O.S: 6:1</p>	3	8 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-019	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
F 15 Z 9588	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p> 	2	8 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES			NO			Was The Examination Carried Out?				
							Within an Interval of 6 Months?	YES	✓	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES			NO			Within an Interval of 12 Months?	YES		NO	✓
		✓					In Accordance with an Examination Scheme?	YES	✓	NO	
	YES			NO			After the Occurrence of Exceptional Circumstances?	YES		NO	✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-020	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
HL 3 115	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	2	8 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date:
--	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-021	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
B 7127 B 7128 B 7129 B 7230 B 202 A 5066 A 5067 A 5069 A 4166 02	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1</p> 	10	6 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-022	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
HL 012 HL 99033 50 51 651 652 653 654 655 656 HL 65 111	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8”</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> 	12	6 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?				Was The Examination Carried Out?					
	YES		NO	√	Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?					Within an Interval of 12 Months?	YES		NO	√
	YES	√	NO		In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:

Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-023	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
657 H 22 019 01 HL 65 888	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8”</p> <p>GRADE: 6</p> <p>Manufactured: DY</p> <p>F.O.S: 6:1</p> 	6	6 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-024	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
110 HL 29 52	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8”</p> <p>GRADE: 6</p> <p>Manufactured: DSL</p> <p>F.O.S: 6:1</p> 	3	6 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> 	Authenticated By: <p align="center">Majd Dayoub</p> 	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	11-May-2024
Certificate Number:	ATS-05-24-3200-025	Next Date of Examination:	10-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL
GWOA4 098	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p>	2	6 1/2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES Has The Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	√	

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **NONE**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:
Items Mentioned-Above was Inspected Visually and Dimensionally At The Time of Inspection:

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
--	---	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021

