



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-068	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 1800	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: Soft Eye at Both Ends, Dim: 36 mm (L) X 6 M F.O.S: 5:1</p>	01	13.1 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?	YES	√	NO	
					Within an Interval of 6 Months?	YES		NO	√
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEAA Registered Technician	Authenticated By:  Majd Dayoub	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-069	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
12 / 18	<p><u>FOUR-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: C/W Master Link on Top: Hard Eye at Both Ends, Dim: 13 mm (L) X 4 M F.O.S: 5:1</p>	01	4.4 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	✓	Was The Examination Carried Out?	YES	✓	NO	
					Within an Interval of 6 Months?	YES		NO	✓
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	✓	NO		Within an Interval of 12 Months?	YES		NO	✓
					In Accordance with an Examination Scheme?	YES	✓	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-070	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 4444	<p><u>FOUR-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: C/W Master Link on Top: Hard Eye at Both Ends, Dim: 10 mm (L) X 1.5 M F.O.S: 5:1</p>	01	2.7 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?	YES	√	NO	
					Within an Interval of 6 Months?	YES		NO	√
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-071	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 5624 B 5625 B 5626 B 5627	<u>TWO-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: C/W Master Link on Top: Hard Eye at Both Ends, Dim: 13 mm (L) X 1 M F.O.S: 5:1	04	2.9 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None	YES		
	NO		
Is The Above a Defect Which is of Immediate Danger to Persons:	YES by		
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-072	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
GY18114838 GY18114837	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 19 mm (L) X 4 M F.O.S: 5:1	02	45.8 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			NO
Is The Above a Defect Which is of Immediate Danger to Persons:			NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-073	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 1801	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye X Soft Eye, Dim: 32 mm (L) X 6 M F.O.S: 5:1</p>	01	13.1 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-074	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 3931 B 3932	<u>FOUR-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: C/W Master Link on Top: Hard Eye at Both Ends, Dim: 16 mm (L) X 2 M F.O.S: 5:1	02	6.9 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?					
					Within an Interval of 6 Months?		YES	√	NO	
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?		YES		NO	√
					In Accordance with an Examination Scheme?		YES	√	NO	
					After the Occurrence of Exceptional Circumstances?		YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-075	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
22159002	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: Thimble Eye X Plain Ends, Dim: 16 mm (L) X 90 M F.O.S: 5:1</p>	01	3 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**


Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By:  Majd Dayoub	Stamp and Date: 

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-076	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 1521	<p><u>FOUR-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: C/W Master Link on Top: Hard Eye X Soft Eye, Dim: 22 mm (L) X 8 M F.O.S: 5:1</p>	01	13 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	✓		In Accordance with an Examination Scheme?
			After the Occurrence of Exceptional Circumstances?
			YES
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			
Is The Above a Defect Which is of Immediate Danger to Persons:		YES	NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:		YES by	
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?		YES	NO
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
<p>Hasan Omran</p> <p>ASNT LEVEL II (VT, MT, PT, UT)</p> <p>LEEA Registered Technician</p>	<p>Majd Dayoub</p>		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-077	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 8808	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 19 mm (L) X 18 M F.O.S: 5:1</p>	01	4.6 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			NO
Is The Above a Defect Which is of Immediate Danger to Persons:			NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
<p>Hasan Omran</p> <p>ASNT LEVEL II (VT, MT, PT, UT)</p> <p>LEEA Registered Technician</p>	<p>Majd Dayoub</p>		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-078	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
GY23055869	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye with Plan End, Dim: 16 mm (L) X 90 M F.O.S: 5:1</p>	01	29 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			NO
Is The Above a Defect Which is of Immediate Danger to Persons:			NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
<p>Hasan Omran</p> <p>ASNT LEVEL II (VT, MT, PT, UT)</p> <p>LEEA Registered Technician</p>	<p>Majd Dayoub</p>		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-079	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 9576 B 9577	<u>TWO-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: C/W Master Link on Top: Hard Eye at Both Ends, Dim: 22 mm (L) X 8 M F.O.S: 5:1	02	8.7 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	✓		YES
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None	YES	NO	In Accordance with an Examination Scheme?
	✓		YES
Is The Above a Defect Which is of Immediate Danger to Persons:	YES	NO	After the Occurrence of Exceptional Circumstances?
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		YES
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-080	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
B 9578 B 9579 B 9580 B 9581	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 19 mm (L) X 3 M F.O.S: 5:1	04	4.6 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			NO
Is The Above a Defect Which is of Immediate Danger to Persons:			NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub		Stamp and Date:

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-081	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
C 108 C 109 C 110 C 111 C 112 C 113 C 114 C 115 C 116 C 117	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 16 mm (L) X 1.2 M F.O.S: 5:1	10	3.3 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months? YES ✓ NO
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months? YES NO ✓
	✓		In Accordance with an Examination Scheme? YES ✓ NO
			After the Occurrence of Exceptional Circumstances? YES NO ✓
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			
Is The Above a Defect Which is of Immediate Danger to Persons:		YES	NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:		YES by	
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?		YES	NO
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-082	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
C 118 C 119 C 120 C 121 C 122 C 123 C 124 C 125 C 126 C 127	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 16 mm (L) X 1.2 M F.O.S: 5:1	10	3.3 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	✓		In Accordance with an Examination Scheme?
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None	YES	NO	After the Occurrence of Exceptional Circumstances?
	✓		YES
Is The Above a Defect Which is of Immediate Danger to Persons:	YES	NO	
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-083	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	MBL:
GS1901688 GS1901699	<u>SINGLE-LEG WIRE ROPE GUYLINE</u> IWRC Mechanically Spliced With Spelter Socket: Spelter Socket X Hard Eye, Dim: 20 mm (L) X 38.2 M F.O.S: 5:1	02	211.5 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			NO
Is The Above a Defect Which is of Immediate Danger to Persons:			NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-084	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
ATS1223-001 ATS1223-002	<u>SINGLE-LEG WIRE ROPE GUYLINE</u> IWRC Mechanically Spliced With Spelter Socket: Spelter Socket X Hard Eye, Dim: 16 mm (L) X 36 M F.O.S: 5:1	02	15 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			✓
Is The Above a Defect Which is of Immediate Danger to Persons:	YES	NO	✓
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	✓
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024					
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024					
Certificate Number:	ATS-05-24-3200-085	Next Date of Examination:	11-Nov-2024					
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023					
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:					
ATS1223-004 ATS1223-005	<u>SINGLE-LEG WIRE ROPE SLING</u> GUY LINE IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 16 mm (L) X 38 M F.O.S: 5:1	02	15 KN					
Reference Standards	BS EN 13414-1:2003 + A2:2008							
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	✓	Was The Examination Carried Out?				
				Within an Interval of 6 Months?	YES	✓	NO	
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	✓	NO	Within an Interval of 12 Months?	YES		NO	✓
				In Accordance with an Examination Scheme?	YES	✓	NO	
				After the Occurrence of Exceptional Circumstances?	YES		NO	✓
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None								
Is The Above a Defect Which is of Immediate Danger to Persons:					YES		NO	
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:					YES by			
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:								
Particulars of Any Tests Carried out as Part of The Examination:								
Is This Equipment Fit for Purpose?					YES	✓	NO	
Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician			Authenticated By: Majd Dayoub			Stamp and Date: 		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-086	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
ATS1223-003 ATS1223-006	<u>SINGLE-LEG WIRE ROPE SLING</u> GUY LINE IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 16 mm (L) X 36 M F.O.S: 5:1	02	15 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	✓		In Accordance with an Examination Scheme?
			After the Occurrence of Exceptional Circumstances?
			YES
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			
Is The Above a Defect Which is of Immediate Danger to Persons:		YES	NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:		YES by	
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?		YES	NO
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Hasan Omran <i>(Signature)</i> ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Majd Dayoub <i>(Signature)</i>		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-087	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
ATS1223-007 ATS1223-008	<u>SINGLE-LEG WIRE ROPE SLING</u> GUY LINE IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 20 mm (L) X 21.5 M F.O.S: 5:1	02	20 KN

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?				
					Within an Interval of 6 Months?	YES	√	NO	
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-088	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
ATS1223-009 ATS1223-010	<u>SINGLE-LEG WIRE ROPE SLING</u> GUY LINE IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 16 mm (L) X 20 M F.O.S: 5:1	02	15 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			NO
			NO
Is The Above a Defect Which is of Immediate Danger to Persons:			NO
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?	YES	NO	
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Majd Dayoub		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-089	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
ATS1223-011 ATS1223-012	<u>SINGLE-LEG WIRE ROPE GUYLINES</u> IWRC Mechanically Spliced With Aluminium Ferrules: Hard Eye at Both Ends, Dim: 16 mm (L) X 23 M F.O.S: 5:1	02	15 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	YES
	✓		NO
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None	YES		
	NO		
Is The Above a Defect Which is of Immediate Danger to Persons:	YES	NO	Was The Examination Carried Out?
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:	YES by		Within an Interval of 12 Months?
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:	YES		
Particulars of Any Tests Carried out as Part of The Examination:	NO		
Is This Equipment Fit for Purpose?	YES	NO	In Accordance with an Examination Scheme?
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Majd Dayoub		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-090	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	MBL:
GS1901692 GS1901693	<u>SINGLE-LEG WIRE ROPE GUYLINE</u> IWRC Mechanically Spliced With Spelter Socket: Spelter Socket X Hard Eye, Dim: 16 mm (L) X 20.25 M F.O.S: 5:1	02	135 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	✓		In Accordance with an Examination Scheme?
			After the Occurrence of Exceptional Circumstances?
			YES
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			
Is The Above a Defect Which is of Immediate Danger to Persons:			YES
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:			YES by
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?			YES
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Majd Dayoub		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-091	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023
Serial No: / Asset No:	Description of The Equipment:	Qty:	MBL:
GS1901694 GS1901695	<u>SINGLE-LEG WIRE ROPE GUYLINE</u> IWRC Mechanically Spliced With Spelter Socket: Spelter Socket X Hard Eye, Dim: 16 mm (L) X 20.45 M F.O.S: 5:1	02	135 KN
Reference Standards	BS EN 13414-1:2003 + A2:2008		
Is This The First Examination After Installation or Assembly at a New Site or location?	YES	NO	Was The Examination Carried Out?
		✓	Within an Interval of 6 Months?
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	NO	Within an Interval of 12 Months?
	✓		In Accordance with an Examination Scheme?
			After the Occurrence of Exceptional Circumstances?
			YES
Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: None			
Is The Above a Defect Which is of Immediate Danger to Persons:			YES
Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons:			YES by
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of Any Tests Carried out as Part of The Examination:			
Is This Equipment Fit for Purpose?			YES
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Majd Dayoub		

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	12-May-2024
Location of Examination:	HL-99 – RU-149	Date of Certificate:	12-May-2024
Certificate Number:	ATS-05-24-3200-092	Next Date of Examination:	11-Nov-2024
Job Number:	ATS-05-24-3200	Last Date of Examination:	25-Nov-2023

Serial No: / Asset No:	Description of The Equipment:	Qty:	MBL:
GS1901696	<p align="center"><u>SINGLE-LEG WIRE ROPE GUYLINE</u></p> <p align="center">IWRC Mechanically Spliced With Spelter Socket: Spelter Socket X Plain End, Dim: 11 mm (L) X 66 M F.O.S: 5:1</p>	01	71.1 KN

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	YES		NO	√	Was The Examination Carried Out?	YES	√	NO	
					Within an Interval of 6 Months?	YES		NO	√
If The Answer to The Above Question is YES has the Equipment Been Installed Correctly?	YES	√	NO		Within an Interval of 12 Months?	YES		NO	√
					In Accordance with an Examination Scheme?	YES	√	NO	
					After the Occurrence of Exceptional Circumstances?	YES		NO	√

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **None**

Is The Above a Defect Which is of Immediate Danger to Persons: YES NO

Is The Above a Defect Which is Not Yet But Could Become a Danger to Persons: YES by

Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

Particulars of Any Tests Carried out as Part of The Examination:

Is This Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021