



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-002	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
G1 G11	1-LEG WIRE ROPE SLING (Guy Line) 20 mm Diameter, 38 M Length, Const.6x36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye. FOS: 5:1 Location: crown block	02	4.6 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-003	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
G2 G42	1-LEG WIRE ROPE SLING (Guy Line) 16 mm Diameter, 36 M Length, Const.6x36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Open spelter socket X Hard Eye. FOS: 5:1 Location: crown block	02	3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				Was the examination carried out?					
	YES		NO		Within an interval of 12 months?	YES		NO	√
				Was the examination carried out?					
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?					
				YES		NO	√		

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date **08-06-2024** above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-004	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
G3 G23	1-LEG WIRE ROPE SLING (Guy Line) 16 mm Diameter, 24 M Length, Const.6x36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye. FOS: 5:1 Location: crown block	02	3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date **08-06-2024** above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-005	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
G4 G34	<p>1-LEG WIRE ROPE SLING (Guy Line)</p> <p>16 mm Diameter, 20 M Length, Const.6x36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: crown block</p>	02	3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar </p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By: <p style="text-align: center;"></p> <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-006	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL
GS18121734 GS18121733	1-LEG WIRE ROPE SLING (Guy Line) 11 mm Diameter, 66 M Length, Const.6x36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Open spelter socket X Hard Eye. FOS: 5:1 Location: crown block	02	71.1 KN

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-007	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
G5 G55	<p>1-LEG WIRE ROPE SLING (Guy Line)</p> <p>16 mm Diameter, 36 M Length, Const.6x36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: crown block</p>	02	3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**



Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p>Aram Dlawar</p>  ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date **08-06-2024** above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-008	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C1 C2	<p>1-LEG WIRE ROPE SLING</p> <p>10 mm Diameter, 0.5 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: under rig floor</p>	02	1 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-009	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C3 C4	<p>1-LEG WIRE ROPE SLING</p> <p>06 mm Diameter, 0.68 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: under rig floor(for fall arrestor support)</p>	02	0.5 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar </p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By: <p style="text-align: center;"></p> <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date:
--	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-010	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F36	<p>1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 1.20 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: under rig floor (for flow line)</p>	01	22 KN

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar </p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By: <p style="text-align: center;"></p> <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date:
--	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-011	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C5 C6	<p>1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 8.00 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: manual tong sling</p>	02	4.6 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-012	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C7 C8	<p>1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 23.5 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: monkey board guy line</p>	02	3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar </p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By: <p style="text-align: center;"></p> <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date:
--	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-013	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C9 (A26) C10 (A25)	1-LEG WIRE ROPE SLING 20 mm Diameter, 21.8 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye. FOS: 5:1 Location: power swivel sling	02	45.8 KN

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-014	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C11	<p>1-LEG WIRE ROPE SLING</p> <p>12 mm Diameter, 45 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: escape line from monkey board</p>	01	17 KN

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-015	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C14 C15	<p>1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 0.78 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: fire fighter area, hose support on rig floor</p>	02	3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**


Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar</p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By: <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-016	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C16	<p>1-LEG WIRE ROPE SLING</p> <p>15 mm Diameter, 1.2 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: fire fighter area</p>	01	2.25 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-017	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C12	<p align="center">1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 90 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Equipped with swivel + counterweight + self-locking hook (5.3 T) Free end attached To Hydraulic Winch Drum X Hard Eye.</p> <p>FOS: 5:1 Location: hydraulic winch sling</p>	01	2.7 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar </p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"></p> <p align="center">Meysam Minaei</p>	Stamp and Date:
---	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-018	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S1001	<p>1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 90 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Equipped with swivel + Chain sling(d=16mm) Free end X Hard Eye.</p> <p>FOS: 5:1 Location: hydraulic winch sling</p>	01	2.7 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar <i>(Signature)</i> ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: <i>(Signature)</i> Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-019	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B5302 B5303	1-LEG WIRE ROPE SLING 10 mm Diameter, 36.5 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye. FOS: 5:1 Location: manual tong sling	02	1.3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				Was the examination carried out?					
	YES		NO		Within an interval of 12 months?	YES		NO	√
				Was the examination carried out?					
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?					
				YES		NO	√		

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-020	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A4213	<p>1-LEG WIRE ROPE SLING</p> <p>16 mm Diameter, 3.3 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: bell nipple sling</p>	01	3.3 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**



Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar</p>  <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By:  <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-021	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A10 A11 A12 A13	<p>1-LEG WIRE ROPE SLING</p> <p>26 mm Diameter, 5.2 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: fire fighter area sling</p>	04	8.6 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation
Iraq –Basra – AlBarjisia
Akader@aberdeents.com / inspection@aberdeents-iq.com
Tel: +964 7822222633 / +9647827451212



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-022	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
15126 15120 GY18006883 F004 M1 M2 15121 15123 F003	<p align="center">1-LEG WIRE ROPE SLING</p> <p>22 mm Diameter, 10 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye.</p> <p>FOS: 5:1 Location: sling store</p>	09	5.65 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-023	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
M3 M4 M5 HL01	<p>1-LEG WIRE ROPE SLING</p> <p>30 mm Diameter, 12.1 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye.</p> <p>FOS: 5:1 Location: sling store</p>	04	10 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-024	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A9620 B6147 B6144 M5 B6145 B6146	1-LEG WIRE ROPE SLING 36 mm Diameter, 6.00 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: sling store	06	16.6 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-025	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B9336 A9622 B9361 B9364 B9362	1-LEG WIRE ROPE SLING 36 mm Diameter, 6.00 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Hard Eye. FOS: 5:1 Location: sling store	05	16.6 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date & swl above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-001	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A6420	<p>4-LEG WIRE ROPE SLING</p> <p>19 mm Diameter, 1.5 M Length, Const.6×36, IWRC, RHO, Galv Steel MECHANICALLY SPLICED WITH ALUMINUM FERRULE. C/W MASTER LINK ASSEMBLY. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: cement block</p>	01	7.8 T

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO




Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p style="text-align: center;">Aram Dlawar</p>  <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;">LEEA Registered Technician</p>	Authenticated By:  <p style="text-align: center;">Meysam Minaei</p>	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021