




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-002	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F84 G41 HYF8 HL4 D66	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	05	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-003	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B1525	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: TOYOLIFT F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-004	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
W48	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 8 Manufactured: J&L F.O.S: 6:1</p>	01	12.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-005	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
MF790C	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: APL F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-006	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-007	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H9 H44 105	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	03	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-008	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
12 A110	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1/2” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	02	2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-009	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
448	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-010	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
2	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √



Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-011	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B7 K1 A1	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	03	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-012	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
0211	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-013	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
3	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: MCKAT F.O.S: 6:1</p>	01	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-014	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A82H	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-015	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
103 A551	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	02	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-016	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H112	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with 4 columns: Client Name, Location of Examination, Certificate Number, Job Number, Date of Examination, Date of Certificate, Last Examination Date, Next Date of Examination.

Table with 4 columns: Serial No. / Asset No., Description of The Equipment, Qty., SWL. Includes details for BOW SHACKLE and technical diagrams.

Reference Standards: BS EN 13889:2003 + A1:2008

Table with 4 columns: Question, YES, NO, Was the examination carried out? Includes questions about first examination and installation correctness.

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: none

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons: YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection. Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar, ASNT LEVEL II (VT, MT, PT, UT), LEEA Registered Technician. Authenticated By: Meysam Minaei. Stamp and Date: ABERDEEN TECHNICAL SERVICES logo.

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-018	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
15726	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p>	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-019	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-06-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S2	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme? YES ✓ NO After the occurrence of exceptional circumstances? YES NO ✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	✓
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	✓	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-020	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
BSY99	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO




Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-021	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F3859	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: BASH-P F.O.S: 6:1</p>	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-022	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-06-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A878	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme? YES ✓ NO After the occurrence of exceptional circumstances? YES NO ✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	✓
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	✓	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-023	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A3	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: DSL F.O.S: 6:1</p>	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	09-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	09-06-2024
Certificate Number:	ATS-06-24-3466-024	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	08-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B1 B8	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	02	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-025	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B81	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	08-06-2024
Location of Examination:	HL 100 – R-608	Date of Certificate:	08-06-2024
Certificate Number:	ATS-06-24-3466-001	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	07-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
OS104B	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021

