



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL-100, Job Number, ATS-06-24-3466

Table with 5 columns: Date of Examination, 09-06-2024, Date of Report, 09-06-2024, Certificate No, ATS-06-24-3466-002

Main equipment table with columns: Pad Eyes S/N, QTY, Description, SWL, Date of last Thorough examination. Includes a photo of a pad eye.

Reference Standard: LEEA DOC 048:2015

Inspection questions table with columns for YES/NO and checkmarks.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, API RP 4G & ASTM E709, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, etc.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE. Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Signature table with columns: Name of Inspector, Name of person authenticating this report, Latest date by which next thorough examination must be carried out: 08-12-2024

