




**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-028	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
31	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 7/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: J&amp;L</b>  <b>F.O.S: 6:1</b></p> 	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-029	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A15	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 7/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: DSL</b>  <b>F.O.S: 6:1</b></p>	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-030	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
110	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: J&amp;L</b>  <b>F.O.S: 6:1</b></p> 	01	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HILONG 100 / R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-031	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
E14	<p align="center"><b>DEE SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8" <b>GRADE:</b> 6 <b>Manufactured:</b> J&amp;L <b>F.O.S:</b> 6:1</p> 	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Aram Dlawar:</b> ASNT LEVEL II VT, MT, PT, UT LEEA	<b>Authenticated By:</b>   Meysam Minaei	<b>Stamp and Date:</b> 
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-032	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B12 B2	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b> <b>GRADE: 6</b> <b>Manufactured: J&amp;L</b> <b>F.O.S: 6:1</b></p> 	02	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-033	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C21 23	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1/2” <b>GRADE:</b> 6 <b>Manufactured:</b> J&amp;L <b>F.O.S:</b> 6:1</p>	02	2 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-034	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B2090	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: Toyolift</b>  <b>F.O.S: 6:1</b></p>	01	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-035	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
10	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: J&amp;L</b>  <b>F.O.S: 6:1</b></p>	01	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-036	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A53 A101	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 5/8” <b>GRADE:</b> 6 <b>Manufactured:</b> J&amp;L <b>F.O.S:</b> 6:1</p> 	02	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-037	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A6422	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1”  <b>GRADE:</b> 6  <b>Manufactured:</b> Toyolift  <b>F.O.S:</b> 6:1</p>	01	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-038	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B8 K5	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b> <b>GRADE: 6</b> <b>Manufactured: J&amp;L</b> <b>F.O.S: 6:1</b></p> 	02	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-039	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
018	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4”  <b>GRADE:</b> 6  <b>Manufactured:</b> KEPRO  <b>F.O.S:</b> 6:1</p> 	01	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-040	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A6424 C410 C409 C407 A4175	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b> <b>GRADE: 6</b> <b>Manufactured: Toyolift</b> <b>F.O.S: 6:1</b></p>	05	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-041	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
37	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b>  <b>GRADE: 6</b>  <b>Manufactured: J&amp;L</b>  <b>F.O.S: 6:1</b></p> 	01	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO



Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-042	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A221 C412 C411	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4” <b>GRADE:</b> 6 <b>Manufactured:</b> Toyolift <b>F.O.S:</b> 6:1</p>	03	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-043	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1013	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/2”  <b>GRADE:</b> 6  <b>Manufactured:</b> XW  <b>F.O.S:</b> 6:1</p>	01	17 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-044	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S297B	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/2”  <b>GRADE:</b> 6  <b>Manufactured:</b> Crosby  <b>F.O.S:</b> 6:1</p> 	01	17 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-045	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL0010	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4”  <b>GRADE:</b> 6  <b>Manufactured:</b> Crosby  <b>F.O.S:</b> 6:1</p>	01	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-046	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1100 A655 106	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b> <b>GRADE: 6</b> <b>Manufactured: J&amp;L</b> <b>F.O.S: 6:1</b></p>	03	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-047	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
4 H3	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 3/4"</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> J&amp;L</p> <p><b>F.O.S:</b> 6:1</p>	02	4.75 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-048	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL6	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 7/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: J&amp;L</b>  <b>F.O.S: 6:1</b></p> 	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO



Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-049	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B6150	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 7/8"</b>  <b>GRADE: 6</b>  <b>Manufactured: Toyolift</b>  <b>F.O.S: 6:1</b></p> 	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-050	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H10	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 3/4”  <b>GRADE:</b> 6  <b>Manufactured:</b> DY  <b>F.O.S:</b> 6:1</p> 	01	4.75 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Date of Examination (10-06-2024), Location of Examination (HILONG 100 / R-055), Date of Certificate (10-06-2024), Certificate Number (ATS-06-24-3466-026), Last Examination Date (Jan-2024), Job Number (ATS-06-24-3466), Next Date of Examination (09-Dec-2024)

Table with equipment details: Serial No./Asset No (184, A8, A81, FS86, A7), Description of The Equipment (DEE SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin), Qty (05), SWL (6.5 Ton). Includes technical drawing of the shackle with dimensions A, B, C, D.

Reference Standards: BS EN 13889:2003+A1:2008

Table with examination questions: 'Is this the first examination after installation or assembly at a new site or location?', 'If the answer to the above question is YES has the equipment been installed correctly?'. Includes 'Was the examination carried out?' section with frequency options (6 months, 12 months) and conditions (examination scheme, exceptional circumstances).

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons? YES NO ✓

Is the above a defect which is not yet but could become a danger to persons? YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose? YES ✓ NO

Table with signatures: Inspector Name, Qualifications & signature (Aram Dlawar, ASNT LEVEL II, VT, MT, PT, UT, LEEA); Authenticated By (Meysam Minaei); Stamp and Date (Aberdeen Technical Services stamp).

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	10-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	10-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-027	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
FS87 A83	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b> <b>GRADE: 6</b> <b>Manufactured: J&amp;L</b> <b>F.O.S: 6:1</b></p>	02	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021