




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-052	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B03 014 026	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4"</p> <p>GRADE: 6</p> <p>Manufactured: HK</p> <p>F.O.S: 6:1</p> 	03	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-053	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
D30 HL6	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p> 	02	9.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-054	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
5	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-055	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A002 FS60 6	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	03	6.5 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-056	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
7 FS14 F31 FS3	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/2" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	04	17 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Aram Dlawar:  ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-057	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL100-003 HL100-004 HL100-005 HL100-006	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 3/4" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	04	25 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Meysam Minaei	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-058	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
627	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8"</p> <p>GRADE: 6</p> <p>Manufactured: Crosby</p> <p>F.O.S: 6:1</p> 	01	9.5 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	✓	Within an interval of 6 months?	YES	✓	NO	
				Within an interval of 12 months?	YES		NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO		In accordance with an examination scheme?	YES	✓	NO	
					After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	✓
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	✓	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-059	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
D1332	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: BASH-P F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-060	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
2SH	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: CANADA F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO


Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-061	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A001	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-062	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A2 FS8	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	02	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-063	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1001 A4	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	02	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-064	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A1 11 62 FS11 H6 109 B4 HL87 HL1104 1102 118	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8"</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p> 	11	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?				
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-065	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A856 B1523 B152	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1</p> 	03	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Meysam Minaei	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-066	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1004	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/2” GRADE: 6 Manufactured: XW F.O.S: 6:1</p> 	01	17 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**




Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-067	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
K8303	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO




Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-068	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
K85	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: GT6 F.O.S: 6:1</p> 	01	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-069	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL1801-01	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 2 1/2” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	55 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-070	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
113 141189 141138	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: DY F.O.S: 6:1</p> 	03	3.25 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Aram Dlawar:  ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-071	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1002	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**




Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-072	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H8	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	01	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO



Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

<p>Inspector Name, Qualifications & signature:</p> <p align="center">Aram Dlawar </p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	<p>Authenticated By:</p> <p align="center"></p> <p align="center">Meysam Minaei</p>	<p>Stamp and Date:</p> 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-073	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B7984 B2212	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1</p> 	02	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: <i>Meysam Minaei</i> Meysam Minaei	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-074	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B03	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4” GRADE: 6 Manufactured: HK F.O.S: 6:1</p> 	01	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By:  <p align="center">Meysam Minaei</p>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	11-06-2024
Location of Examination:	HILONG 100 / R-055	Date of Certificate:	11-06-2024
Certificate Number:	ATS-06-24-3466-075	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	10-Dec-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
112	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4" GRADE: 6 Manufactured: CG F.O.S: 6:1</p> 	01	4.75 Ton

Reference Standards	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme? YES ✓ NO After the occurrence of exceptional circumstances? YES NO ✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	✓
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	✓	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Aram Dlawar: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By:  Meysam Minaei	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	10-06-2024
Location of Examination:	HL 100 – R-055	Date of Certificate:	10-06-2024
Certificate Number:	ATS-06-24-3466-051	Last Examination Date:	Jan-2024
Job Number:	ATS-06-24-3466	Next Date of Examination:	09-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL0013	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4” GRADE: 6 Manufactured: Crosby F.O.S: 6:1</p>	01	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Meysam Minaei</p>	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021