




**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-092	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
111 B9 B7 333 B5 H11 K6 B6 H49 A556	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: J&amp;L</b></p> <p><b>F.O.S: 6:1</b></p> <p><b>Location: Service Line</b></p> 	10	3.25 Ton

**Reference Standards** BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES √ NO

<p><b>Inspector Name, Qualifications &amp; signature:</b></p> <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p> 	<p><b>Authenticated By:</b></p> <p align="center">Meysam Minaei</p> 	<p><b>Stamp and Date:</b></p> 
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-093	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
25 A5 B4 222 A552 112 1 2 3 4	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: J&amp;L</b></p> <p><b>F.O.S: 6:1</b></p> <p><b>Location: Service line</b></p> 	10	3.25 Ton

**Reference Standards** BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**




Is the above a defect which is of immediate danger to persons **YES** **NO** √

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? **YES** √ **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-094	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
8	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 5/8”  <b>GRADE:</b> 6  <b>Manufactured:</b> Toyolift  <b>F.O.S:</b> 6:1  <b>Location:</b> Service line</p> 	01	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p> 	<b>Stamp and Date:</b> 
---	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-095	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
9	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1/2”</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> J&amp;L</p> <p><b>F.O.S:</b> 6:1</p> <p><b>Location:</b> Service line</p> 	01	2 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons **YES**  **NO**




Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:

*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? **YES**  **NO**

<p><b>Inspector Name, Qualifications &amp; signature:</b></p> <p align="center">Aram Dlawar</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p> 	<p><b>Authenticated By:</b></p> <p align="center">Meysam Minaei</p> 	<p><b>Stamp and Date:</b></p> 
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-096	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B6149	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8”  <b>GRADE:</b> 6  <b>Manufactured:</b> Toyolift  <b>F.O.S:</b> 6:1  <b>Location:</b> turn buckle on carrier substructure</p> 	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**




Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-097	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
777	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8”  <b>GRADE:</b> 6  <b>Manufactured:</b> Crosby  <b>F.O.S:</b> 6:1  <b>Location:</b> turn buckle on carrier substructure</p> 	01	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons **YES** **NO** √

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? **YES** √ **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-098	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1006/A	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4”</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> GP</p> <p><b>F.O.S:</b> 6:1</p> <p><b>Location:</b> turn buckle on carrier substructure</p> 	01	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**




Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p> 	<b>Stamp and Date:</b> 
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-099	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H110	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1/2”  <b>GRADE:</b> 6  <b>Manufactured:</b> J&amp;L  <b>F.O.S:</b> 6:1  <b>Location:</b> Service line</p> 	01	2 Ton

**Reference Standards** BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center">Meysam Minaei</p> 	<b>Stamp and Date:</b> 
---	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HILONG 100 / R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-100	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A22	<p align="center"><b>DEE SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 5/8"  <b>GRADE:</b> 6  <b>Manufactured:</b> DY65  <b>F.O.S:</b> 6:1</p> <p><b>Location:</b> service line</p> 	01	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme? YES ✓ NO After the occurrence of exceptional circumstances? YES NO ✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:			
Is the above a defect which is of immediate danger to persons	YES		NO ✓
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination:			
Is this Equipment Fit for Purpose?	YES	✓	NO

<b>Inspector Name, Qualifications &amp; signature:</b> <u>Aram Dlawar:</u> ASNT LEVEL II VT, MT, PT, UT LEEA	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HILONG 100 / R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-101	<b>Last Examination Date:</b>	Jan-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
47H	<p align="center"><b>DEE SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/8"</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> HK</p> <p><b>F.O.S:</b> 6:1</p> <p><b>Location:</b> turn buckle of carrier</p> 	01	9.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003+A1:2008
----------------------------	--------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme? YES ✓ NO After the occurrence of exceptional circumstances? YES NO ✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:			
Is the above a defect which is of immediate danger to persons	YES		NO ✓
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination:			
Is this Equipment Fit for Purpose?	YES	✓	NO

<b>Inspector Name, Qualifications &amp; signature:</b> <u>Aram Dlawar:</u> ASNT LEVEL II VT, MT, PT, UT LEEA	<b>Authenticated By:</b>  Meysam Minaei	<b>Stamp and Date:</b> 
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	23-06-2024
<b>Location of Examination:</b>	HL 100 – R-055	<b>Date of Certificate:</b>	23-06-2024
<b>Certificate Number:</b>	ATS-06-24-3466-091	<b>Last Examination Date:</b>	JAN-2024
<b>Job Number:</b>	ATS-06-24-3466	<b>Next Date of Examination:</b>	22-12-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL19	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 5/8”  <b>GRADE:</b> 6  <b>Manufactured:</b> DY82  <b>F.O.S:</b> 6:1  <b>Location:</b> Service line</p> 	01	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center">Aram Dlawar</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>   <p align="center">Meysam Minaei</p>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021