




Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-06-24-3466- MPI-008
Rig Number:	HL100	Job No:	ATS-06-24-3466
Location:	Northern Rumila – R-055	Page No:	01 of 01
Date of Inspection:	10-06-2024	Next Inspection Date:	09-12-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444
PICTORIAL:		Item Description: Hydraulic power tong	
		Unit Serial Number: 18025	
		Details of inspection method(s): Visible magnetic particle inspection	
		Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AREAS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.	
		Remarks: ACCEPTED	
Inspection Equipment Details			Personnel Details
Equipment	Ac yoke		Inspector: Aram Dlawar
Serial Number	201504044		Qualifications ASNT LEVEL II
Calibration Date:	05-01-2024		Date: 10-06-2024
Calibration Due:	04-07-2024		Signature: 
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor: Meysam Minaei
Maker and Model	FLUXO	FLUXO	Date: 11-06-2024
Type:	WCP-4	Black magnetic ink-3	
Batch Number	L230523/1	L230125/3	
Expiry Date:	23-05-2028	25-1-2025	
			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633