



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-06-24-3466- MPI-010										
Rig Number:	HL100	Job No:	ATS-06-24-3466										
Location:	Northern Rumila – R-055	Page No:	01 of 01										
Date of Inspection:	12-06-2024	Next Inspection Date:	11-12-2024										
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444										
PICTORIAL:		Item Description: security guard camp											
		<table><tr><td>SN</td><td>01</td><td>02</td><td>03</td><td>04</td></tr><tr><td>SWL</td><td colspan="4">10 T</td></tr></table>		SN	01	02	03	04	SWL	10 T			
		SN	01	02	03	04							
		SWL	10 T										
		Unit Serial Number: SGC-1											
Details of inspection method(s): Visible magnetic particle inspection													
Inspection Results: MPI WAS CARRIED OUT ON THE WELDING AND CRITICAL AREAS OF THE LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.													
Remarks: ACCEPTED													
Inspection Equipment Details		Personnel Details											
Equipment	Ac yoke	Inspector:	Aram Dlawar										
Serial Number	201504044	Qualifications	ASNT LEVEL II										
Calibration Date:	05-01-2024	Date:	12-06-2024										
Calibration Due:	04-07-2024	Signature:											
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:										
Maker and Model	FLUXO	FLUXO	Meysam Minaei										
Type:	WCP-4	Black magnetic ink-3	Date:										
Batch Number	L230523/1	L230125/3	13-06-2024										
Expiry Date:	23-05-2028	25-1-2025											
		Company Stamp											
													

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com
Tel: +964 7833334444 +964 7822222633