



# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-06-24-3466- MPI-037	
Rig Number:	HL100	Job No:	ATS-06-24-3466	
Location:	Northern Rumila – R-055	Page No:	01 of 01	
Date of Inspection:	12-06-2024	Next Inspection Date:	11-12-2024	
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444	
<b>PICTORIAL:</b>		<b>Item Description: container store</b>		
		<b>Unit Serial Number: GESU3069448</b>		
		<b>Details of inspection method(s):</b> Visible magnetic particle inspection		
		<b>Inspection Results:</b> MPI WAS CARRIED OUT ON THE WELDING AND CRITICAL AREAS OF THE LIFTING POINTS ( <b>LOWER ISO BLOCKS</b> ) OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.		
<b>Remarks: ACCEPTED</b>				
<b>Inspection Equipment Details</b>			<b>Personnel Details</b>	
<b>Equipment</b>	Ac yoke		Inspector:	Aram Dlawar
Serial Number	201504044		Qualifications	ASNT LEVEL II
Calibration Date:	05-01-2024		Date:	12-06-2024
Calibration Due:	04-07-2024		Signature:	
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION			Supervisor:
Maker and Model	FLUXO	FLUXO	Date:	
Type:	WCP-4	Black magnetic ink-3		
Batch Number	L230523/1	L230125/3		
Expiry Date:	23-05-2028	25-1-2025		
				<b>Company Stamp</b>

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)

Tel: +964 7833334444 +964 782222633