




Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-06-24-3466- MPI-039
Rig Number:	HL100	Job No:	ATS-06-24-3466
Location:	Northern Rumila – R-055	Page No:	01 of 01
Date of Inspection:	12-06-2024	Next Inspection Date:	11-12-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444
PICTORIAL:			Item Description: container store
			Unit Serial Number: GESU3283594
			Details of inspection method(s): Visible magnetic particle inspection
			Inspection Results: MPI WAS CARRIED OUT ON THE WELDING AND CRITICAL AREAS OF THE LIFTING POINTS (LOWER ISO BLOCKS) OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.
			Remarks: ACCEPTED
Inspection Equipment Details		Personnel Details	
Equipment	Ac yoke	Inspector:	Aram Dlawar
Serial Number	201504044	Qualifications	ASNT LEVEL II
Calibration Date:	05-01-2024	Date:	12-06-2024
Calibration Due:	04-07-2024	Signature:	
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:
Maker and Model	FLUXO	FLUXO	Meysam Minaei
Type:	WCP-4	Black magnetic ink-3	Date:
Batch Number	L230523/1	L230125/3	13-06-2024
Expiry Date:	23-05-2028	25-1-2025	
Company Stamp			
			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633