




Certificate of Test and Thorough Examination of Lifting Equipment – Manual Chain Block

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Owner name and address:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination	16-07-2024
Location of Examination:	HILONG RIG 99 / RU386	Date of Certificate:	16-07-2024
Certificate Number:	ATS-07-24-4007-003	Job Number:	ATS-07-24-4007
Date of Manufacture.:	2021-07	Next Date of Examination:	15-01-2025
SWL:	15 TON	Serial No.:	XB17251460
Description of equipment	Manually Operated Chain Block Manufacture: Walsall England Type / Model: HSZ-A Chain Size: 10 mm Number of falls: 8 Grade: 80 / (T) Lifting Range: 6 M		
Reference Standards	BS EN 13157:2004+A1:2009 / ASME B30.7		
Testing Details:	Pass	Fail	Notes
Functional (No Load)	✓		Conducted and found satisfactory
Operational Test (Rated Capacity)	✓		Conducted at rated capacity and found satisfactory
Light Load Test (2% - 10% x Rated Capacity)	✓		Conducted at 5% of rated capacity and found satisfactory
Proof Load Test (1.5 x Rated Capacity)	N/A		-
Last Inspection Date	Next Inspection Due Date	Last Proof Load Test Date	Next Proof Load Test Due
Jan - 2024	15-01-2025	By manufacturer	AFTER ANY Major REPAIR/MODIFICATION
Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
Was the examination carried out:			
Within an interval of 6 months?		YES	✓
Within an interval of 12 months?		YES	NO
In accordance with an examination scheme?		YES	✓
After the occurrence of exceptional circumstances?		YES	NO
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None			
Is the Above A Defect Which Is of Immediate Danger to Persons		YES	NO
Is the Above A Defect Which Is Not Yet but Could Become A Danger to Persons: (If YES State the Date by When)		NO	YES
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: None			
Particulars of Any Tests Carried Out as Part of The Examination: (If None State NONE) In the light of inspection findings chain block was Inspected visually, operationally, and functionally where no defects observed during the test. Hence, it was found satisfactory and fit for intended use.			
Is This Equipment Safe to Operate?		Yes Accept	✓ No Reject
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Aram Dlawar NDT Level II (VT, MT, PT, UT) LEEA Registered Technician	Meysam Minaei		

HIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Thorough Examination of Cahin Block - Checklist

Owner name and address:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination	16-07-2024
Location of Examination:	HILONG RIG 99 / RU386	Date of Certificate:	16-07-2024
Certificate Number:	ATS-07-24-4007-003	Job Number:	ATS-07-24-4007
Date of Manufacture.:	2021-07	Next Date of Examination:	15-01-2025
SWL:	15 TON	Serial No.:	XB17251460

Inspected item / Point	Comments	Accept	Reject
Marking		√	
Body condition		√	
Casing		√	
Top hook		√	
Bottom hook		√	
Hooks safety latches		√	
Hooks swivel		√	
Load chain and Load Chain Sprockets		√	
Loose end anchor pins		√	
Hand chain and Hand chain wheel		√	
Side plates		√	
Brake operating condition		√	
Functionality of the chain hoist		√	

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Aram Dlawar NDT Level II (VT, MT, PT, UT) LEEA Registered Technician	Meysam Minaei	