



# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-08-24-4132- FL-06
Rig Number:	HL100	Job No:	ATS-08-24-4132
Location:	Northern Rumila – R 026	Page No:	01 of 01
Date of Inspection:	18-08-2024	Next Inspection Date:	17-02-2025
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444

**PICTORIAL:**



**Item Description:**

**Wheeled Loader Forklift – Attachment:**  
**Extension Jib with Hook – SN: 11809002**  
**SWL: 5.0 Tonnes**

**Forklift Serial Number:**  
 XUG0500KVJCB11867

**Details of inspection method(s):**  
 Visible magnetic particle inspection

**Inspection Results:**  
 MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

**Remarks: ACCEPTED**

Inspection Equipment Details			Personnel Details		Company Stamp
<b>Equipment</b>	Ac yoke		Inspector:	Hasan Omran	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	28-06-2024		Date:	18-08-2024	
Calibration Due:	27-12-2024		Signature:		
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION		Supervisor:	Majd Dayoub	
Maker and Model	FLUXO	FLUXO	Date:	18-08-2024	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-ig.com](mailto:inspection@aberdeents-ig.com)

Tel: +964 7833334444 +964 782222633