



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL-100, Job Number: ATS-08-24-4132

Table with examination details: Date of Examination: 10-08-2024, Date of Report: 10-08-2024, Certificate No: ATS-08-24-4132-MPI-040

Main table with columns: Pad Eyes S/N, QTY, Description, SWL, Date of last Thorough examination. Includes photos of pad eyes.

Reference Standard: LEEA DOC 048:2015. Inspection questions and answers regarding examination frequency and safety.

Defect identification section: Identification of any part found to have a defect... IS THIS EQUIPMENT SAFE TO OPERATE?

NDT Equipment Details table listing tools like Yoke, Vernier Caliper, White Contrast, Black Ink with their standards and due dates.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection.

Inspector and authenticator details: Name of Inspector: Aram Dlawar, Name of person authenticating this report: Hasan Omran. Includes latest date for next examination: 09-02-2025.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL-100, Job Number: ATS-08-24-4132

Table with examination details: Date of Examination: 10-08-2024, Date of Report: 10-08-2024, Certificate No: ATS-08-24-4132-MPI-040

Main table with columns: Pad Eyes S/N, QTY, Description, SWL, Date of last Thorough examination. Includes details for HL-03 and HL-04, and two photographs of pad eyes.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and safety.

Defect identification section: Identification of any part found to have a defect... IS THIS EQUIPMENT SAFE TO OPERATE?

NDT Equipment Details table listing standards (ASTM E709), viewing conditions, and due dates for various equipment.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects.

Inspector and authenticator details: Name of Inspector: Aram Dlawar, Name of person authenticating this report: Hasan Omran. Includes latest date for next examination: 09-02-2025.

