



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-09-24-4307-MPI-001										
Rig Number:	HL100	Job No:	ATS-09-24-4307										
Location:	Northern Rumila – R026	Page No:	01 of 01										
Date of Inspection:	21-09-2024	Next Inspection Date:	20-03-2025										
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444										
PICTORIAL:		Item Description: Tools Basket – Lifting Points											
		Tools Basket – Lifting points											
		<table><tr><td>SN:</td><td>01</td><td>02</td><td>03</td><td>04</td></tr><tr><td>SWL:</td><td colspan="4">5T Each</td></tr></table>		SN:	01	02	03	04	SWL:	5T Each			
		SN:	01	02	03	04							
		SWL:	5T Each										
Unit Serial Number: IS922													
Details of inspection method(s): Visible magnetic particle inspection													
		Inspection Results: MPI WAS CARRIED OUT ON THE WELDING AND CRITICAL AREAS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.											
		Remarks: ACCEPTED											
Inspection Equipment Details		Personnel Details		Company Stamp 									
Equipment	Ac yoke	Inspector:	Hasan Omran										
Serial Number	201504044	Qualifications	ASNT LEVEL II										
Calibration Date:	28-06-2024	Date:	21-09-2024										
Calibration Due:	27-12-2024	Signature:											
Consumables	MAGNETIC PARTICLES INSPECTION												
Maker and Model	FLUXO	FLUXO											
Type:	WCP-4	Black magnetic ink-3											
Batch Number	L230523/1	L230125/3											
Expiry Date:	23-05-2028	25-1-2025											
		Supervisor:	Majd Dayoub										
		Date:	21-09-2024										



ATS-NDT-F-001 ISSUE 3 JUN 2023

E: akader@aberdeents.com
inspection@aberdeents-ig.com

Tel: +964 7833334444 +964 7822222633