



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



| | | | |
|---------------------|--|-----------------------|------------------------|
| Client: | Hilong Oil Services & Engineering | Certificate Number: | ATS-11-24-4375- FL-05 |
| Rig Number: | HL99 | Job No: | ATS-11-24-4375 |
| Location: | Southern Rumila – RU264 | Page No: | 01 of 01 |
| Date of Inspection: | 12-11-2024 | Next Inspection Date: | 11-11-2025 |
| Type of Inspection | Visual inspection & MPI (Wet Visible Method) | Ref. Standards: | ASTM E709, ASTM E 1444 |

PICTORIAL:



Item Description:

Wheeled Loader Forklift – Bucket Attachment
SN: 11808004

Forklift Serial Number:
XUG0500KCJCB11866

Details of inspection method(s):
Visible magnetic particle inspection

Inspection Results:
MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

Remarks: **ACCEPTED**

| Inspection Equipment Details | | | Personnel Details | | Company Stamp |
|------------------------------|-------------------------------|----------------------|-------------------|---------------|---------------|
| Equipment | Ac yoke | | Inspector: | Hasan Omran | |
| Serial Number | 201504044 | | Qualifications | ASNT LEVEL II | |
| Calibration Date: | 28-06-2024 | | Date: | 12-11-2024 | |
| Calibration Due: | 27-12-2024 | | Signature: | | |
| Consumables | MAGNETIC PARTICLES INSPECTION | | Supervisor: | Majd Dayoub | |
| Maker and Model | FLUXO | FLUXO | Date: | 13-11-2024 | |
| Type: | WCP-4 | Black magnetic ink-3 | | | |
| Batch Number | L230523/1 | L230125/3 | | | |
| Expiry Date: | 23-05-2028 | 25-1-2025 | | | |

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633