



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-11-24-4375- MPI-020	
Rig Number:	HL99	Job No:	ATS-11-24-4375	
Location:	Southern Rumila – RU264	Page No:	01 of 01	
Date of Inspection:	12-11-2024	Next Inspection Date:	11-05-2025	
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444	
PICTORIAL:		Item Description: Tool Box – Rig Floor		
		Lifting points		
		SN	1	3
		SN	2	4
		SWL	1 Tonnes / Each	
		Unit Serial Number: TB-01		
		Details of inspection method(s): Visible magnetic particle inspection		
		Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.		
		Remarks: ACCEPTED		
Inspection Equipment Details			Personnel Details	
Equipment	Ac yoke		Inspector:	Aram Dlawar
Serial Number	201504044		Qualifications	ASNT LEVEL II
Calibration Date:	28-06-2024		Date:	12-11-2024
Calibration Due:	27-12-2024		Signature:	
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:	Hasan Omran
Maker and Model	FLUXO	FLUXO	Date:	13-11-2024
Type:	WCP-4	Black magnetic ink-3		
Batch Number	L230523/1	L230125/3		
Expiry Date:	23-05-2028	25-1-2025		



ATS-NDT-F-001 ISSUE 3 JUN 2023

E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633