



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-11-24-4375- MPI-023										
Rig Number:	HL99	Job No:	ATS-11-24-4375										
Location:	Southern Rumila – RU264	Page No:	01 of 01										
Date of Inspection:	12-11-2024	Next Inspection Date:	11-05-2025										
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444										
PICTORIAL:		Item Description: Catwalk											
		<table border="1"> <thead> <tr> <th colspan="3">Lifting points</th> </tr> </thead> <tbody> <tr> <td>SN</td> <td>DZ047</td> <td>DZ048</td> </tr> <tr> <td>SN</td> <td>DZ049</td> <td>DZ050</td> </tr> <tr> <td>SWL</td> <td colspan="2">1 Tonnes / Each</td> </tr> </tbody> </table>		Lifting points			SN	DZ047	DZ048	SN	DZ049	DZ050	SWL
Lifting points													
SN	DZ047	DZ048											
SN	DZ049	DZ050											
SWL	1 Tonnes / Each												
		Unit Serial Number: CW-01											
		Details of inspection method(s): Visible magnetic particle inspection											
		Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.											
		Remarks: ACCEPTED											
Inspection Equipment Details			Personnel Details										
Equipment	Ac yoke		Inspector:										
Serial Number	201504044		Qualifications										
Calibration Date:	28-06-2024		Date:										
Calibration Due:	27-12-2024		Signature:										
Consumables	MAGNETIC PARTICLES INSPECTION												
Maker and Model	FLUXO	FLUXO	Supervisor:										
Type:	WCP-4	Black magnetic ink-3	Date:										
Batch Number	L230523/1	L230125/3											
Expiry Date:	23-05-2028	25-1-2025											
			Company Stamp										

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com
 Tel: +964 7833334444 +964 7822222633