

**Certificate of Thorough Examination & NDT of Lifting Equipment**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	RIG-99	Job Number:	ATS-11-24-4375
Date of Examination:	12-11-2024	Date of Next Examination:	11-05-2025	Certificate No:	ATS-11-24-4375-MPI-029

Serial Number:	QTY	Description	SWL	Date of last Thorough examination
18059-5 18059-6 18059-7 18059-8	04	Fabricated Pad Eyes Pad Eye Dimension: Thickness: 23 MM Pin Hole Diameter: 50 MM Length: 200 MM Height: 305 MM Location: mud tank # 18059	50 KN / Each	May-2024
				

Reference Standard:		LEEA DOC 048:2015									
Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?						
	YES		NO	√		YES	√	NO			
						YES		NO	√		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	√	NO			
						YES		NO	√		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE											
Is the above a defect which is of immediate danger to persons:						YES		NO			
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE											
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√	NO			

NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	AC yoke	Serial No:	201504044	Due Date	27-12-2024
Vernier Caliper	Digital	Serial No:	8914	Due Date	27-12-2024
White Contrast	FLUXO: WCP-4	Batch No:	L230523/1	Due Date	23-May-2028
Black Ink	FLUXO: Black magnetic ink-3	Batch No:	L230125/3	Due Date	25-Jan-2025

NDT Results	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect: NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	

Name of Inspector:	Name of person authenticating this report:
Aram Dlawar ASNT NDT Level II (VT, MT, AUT) LEEAA Registered Technician	Hasan Omran

