



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-11-24-4375- MPI-111	
Rig Number:	HL99	Job No:	ATS-11-24-4375	
Location:	Southern Rumila – RU264	Page No:	01 of 01	
Date of Inspection:	14-11-2024	Next Inspection Date:	13-05-2025	
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444	
PICTORIAL:		Item Description: ISO Container Lifting lugs WLL: at 0° = 12.5 T WLL: at 36° = 10 T WLL: at 50° = 8 T		
		Unit Serial Number: CL6024 + CL5891 + CL5964 + CL6057		
		Details of inspection method(s): Visible magnetic particle inspection		
		Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.		
		Remarks: ACCEPTED		
Inspection Equipment Details		Personnel Details		
Equipment	Ac yoke	Inspector:	Aram Dlawar	
Serial Number	201504044	Qualifications	ASNT LEVEL II	
Calibration Date:	28-06-2024	Date:	14-11-2024	
Calibration Due:	27-12-2024	Signature:		
Consumables	MAGNETIC PARTICLES INSPECTION			
Maker and Model	FLUXO	FLUXO		
Type:	WCP-4	Black magnetic ink-3		
Batch Number	L230523/1	L230125/3		
Expiry Date:	23-05-2028	25-1-2025	Date:	15-11-2024

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633