



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name (Hilong Oil Services & Engineering), Rig Number (RIG-99), Job Number (ATS-11-24-4375), Date of Examination (14-11-2024), Date of Next Examination (13-05-2025), Certificate No. (ATS-11-24-4375-MPI-118)

Table with equipment details: Serial Number (18060-5 to 18060-8), QTY (04), Description (Fabricated Pad Eyes), SWL (50 KN / Each), Date of last Thorough examination (May-2024). Includes photos of the pad eyes and technical specifications like Thickness: 17 MM, Pin Hole Diameter: 35 MM, Length: 139 MM, Height: 120 MM, Location: mud tank # 18060.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and safety.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with NDT Equipment Details: Standard (ASTM E709), Viewing Condition, Colored Media, Method (WET), Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Inspector details: Name of Inspector (Aram Dlawar), Name of person authenticating this report (Hasan Omran), ASNT NDT Level II (VT, MT, AUT), LEEA Registered Technician.

