



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-01-25-4756-MPI-010
Rig Number:	HL-22	Job No:	ATS-01-25-4756
Location:	ZB 647	Page No:	01 of 01
Date of Inspection:	21-01-2025	Next Inspection Date:	20-07-2025
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444

PICTORIAL:



Item Description:

Catwalk Ramp – Rig Floor: Mounting Structure and Connection Points

Serial Number: N/A00

Details of inspection method(s):
Visible magnetic particle inspection

Inspection Results:
MPI WAS CARRIED OUT ON THE WELDING AND CRITICAL AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

Remarks: ACCEPTED

Inspection Equipment Details			Personnel Details		Company Stamp
Equipment	Ac yoke		Inspector:	Hasan Omran	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	24-12-2024		Date:	21-01-2025	
Calibration Due:	23-06-2025		Signature:		
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:	Majd Dayoub	
Maker and Model	FLUXO	FLUXO	Date:	22-01-2025	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523	L230125			
Expiry Date:	23-05-2028	25-1-2028			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com
 Tel: +964 7833334444 +964 7822222633