



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	DPAB Co. Ltd. Iraq Branch / Block-9	Date of Examination:	10-Apr-2025
Location of Examination:	DQ – 010 / Block 9	Date of Certificate:	10-Apr-2025
Certificate Number:	ATS-04-25-4933-012	Next Date of Examination:	09-Oct-2025
Job Number:	ATS-04-25-4933	Last Date of Examination:	-

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
ED-01	<p align="center"><u>Escape Device</u></p> <p>Manufacturer: SALA Date of MFG: 11/2012 Model: 2103144 Lot No: 1438937 Connected with: Low speed descender # 152387</p>	01	822 KGS

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	Within an interval of 12 months?			
	YES		NO	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
 Items mentioned-above was inspected **Visually, Functionally and Dimensionally at the time of inspection**

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub </p>	Stamp and Date: ABERDEEN TECHNICAL SERVICES ABERDEEN TECHNICAL SERVICES 1438937
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021