



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-12-25-5227-MPI-002
Rig Number:	HL-22	Job No:	ATS-12-25-5227
Location:	HL Base – Aberdeen Yard	Page No:	01 of 06
Date of Inspection:	20-12-2025	Next Inspection Date:	19-06-2026
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709

PICTORIAL:



Item Description:

BALL VALVE

Serial Number: Q1101486

Details of inspection method(s):
Visible magnetic particle inspection

Inspection Results:
MPI WAS CARRIED OUT ON THE CRITICAL AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

Remarks: ACCEPTED

Inspection Equipment Details			Personnel Details		Company Stamp
Equipment	Ac yoke		Inspector:	Hasan Omran	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	04-12-2025		Date:	20-12-2025	
Calibration Due:	03-06-2026		Signature:		
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:	Majd Dayoub	
Maker and Model	FLUXO	FLUXO	Date:	21-12-2025	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523	L230125			
Expiry Date:	23-05-2028	25-1-2028			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com
 Tel: +964 7833334444 +964 7822222633